

Parts needed to mount the STOS-MDF extrusion



Extrusion (A)



End caps (B)



Cover (C)




LED strip (D)


NOTE! All LED strips must be connected to a 12 V or 24 V power supply.

IMPORTANT: The manual presents the simplest mounting procedure. More mounting procedures and related accessories can be found at klusdesign.com

1. Mount the LED strip (D), insert the cover (C), and then insert the end cap (B).



2. Apply double-sided tape to the extrusion (A).



3. Connect power, and then attach the extrusion (A) to the surface.

